








Temperature Display

<p>PC-100</p>  <p>Circuit Diagram Model: PC100</p> 	<p>SF-100</p>  <p>Circuit Diagram Model: SF-100</p> 
<p>Temperature display Range: -40~50°C Accuracy: ±1°C</p>	<p>Temperature display Accuracy: ±1°C SF-100P: -40~50°C SF-100H: -5~150°C SF-100: -45~99°C</p>
<p>SF-M01</p> 	<p>SF-M02</p>  <p>Circuit Diagram Model: X-100</p> 
<p>Temperature display Range: -40~50°C</p>	<p>Temperature display Range: -45~99°C</p>